intertek
Total Quality. Assured.

Test Report

NUMBER : TSNH00578176

Applicant : Jiaxing Haifa import and export co., ltd
No.233, Chang 'an North Road, Wuyuan Street, Haiyan County, Jiaxing City, Zhejiang Province
Attn : Lay

Date : Jan 29,2026

Photo:

****

To be continued

Authorized By :
For Intertek Testing Services
(Tianjin) Ltd.

David Zhang
Asst.General Manager

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road, High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

intertek
Total Quality. Assured.

Test Report

NUMBER : TSNH00578176

Sample Description:

One (1) submitted sample said to be

Item Name	: Children electric car
Item No.	: HFTS-9911
P.O. No.	: 24HFE66158
Style No.	: LB-9911
Age grading	: 3-8 years old
Material	: plastic,metal

****

Tests Conducted:

As requested by the applicant, for details refer to attached page(s).

****

To be continued

Authorized By :
For Intertek Testing Services
(Tianjin) Ltd.

David Zhang
Asst.General Manager

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司

1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384

Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

Conclusion：

Tested Samples/components	Standard	Result
Submitted Samples	U.S. ASTM F963-23 Standard Consumer Safety Specification for Toy Safety – Physical and mechanical test and Flammability part	Pass
Submitted Samples	U.S. CFR Title 16 (CPSC Regulations) Mechanical and Physical Tests	Pass
Submitted samples	U.S. Code of Federal Regulations Title 16 Part 1501 – method for identifying toys and other articles intended for use by children under 3 years of age which present choking, aspiration, or ingestion hazards because of small parts.	Not Applicable
Submitted samples	Consumer product safety improvement Act (CPSIA) 2008 section 103 Tracking labels for children products	Pass
Submitted Samples	U.S. CFR Title 16 (CPSC Regulations) Part 1500.3(c)(6)(vi) Flammability Test On Rigid And Pliable Solids	Pass
(1),(2),(3),(4),(5),(6),(7),(8),(9),(10),(11),(12),(13),(14),(15),(16),(17),(18),(19),(20),(21),(22),(23),(24),(25),(26),(27),(28),(29),(30),(31),(32),(33),(34),(35),(36),(37),(38),(39),(40),(42),(43),(44),(45),(46),(47)	ASTM F963:2023-4.3.5.2: Lead Content in Accessible Component Parts	Pass
(41)	Products comply with the following provisions of ASTM F963:2023-4.3 Toxicology: ASTM F963:2023-4.3.5.1: Lead Content in Paint or Similar Surface Coating	Pass
(41)	ASTM F963:2023-4.3.5.2: -Soluble Heavy Metal Content in Surface Coating	Pass
(1),(2),(3),(4),(5),(6),(7),(8),(9),(10),(11),(12),(13),(14),(15),(16),(17),(18),(19),(20),(21),(22),(23),(24),(25),(26),(27),(28),(29),(30),(31),(32),(33),(34),(35),(36),(37),(38),(39),(40)	ASTM F963:2023-4.3.5.2: -Soluble Heavy Metal Content in Substrate	Pass
(41)	U.S. Code of Federal Regulations title 16 part 1303 for total Lead content in surface coating	Pass
(41)	U.S. Consumer Product Safety Improvement Act 2008 title I, section 101 for total Lead content in surface coating	Pass

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road, High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

(1),(2),(3),(4),(5),(6),(7),(8),(9),(10),(11),(12),(13),(14),(15),(16),(17),(18),(19),(20),(21),(22),(23),(24),(25),(26),(27),(28),(29),(30),(31),(32),(33),(34),(35),(36),(37),(38),(39),(40),(42),(43),(44),(45),(46),(47)	U.S. Consumer Product Safety Improvement Act 2008 title I, section 101 for total Lead content in non-surface coating materials (substrate)	Pass
(1),(2),(3),(4),(5),(6),(7),(8),(9),(10),(11),(12),(13),(14),(15),(16),(17),(18),(19),(20),(21),(22),(23),(24),(25),(26),(27),(28),(29),(30),(31),(32),(33),(34),(35),(36),(37),(38),(39),(40),(41)	US Consumer Product Safety Improvement Act 2008 Title I, Sec 108(a) & (b)(3) and US 16 CFR Part 1307 for Prohibition of Children's Toys and Child Care Articles Containing Specified Phthalates	Pass
(1),(2),(3),(4),(5),(6),(7),(8),(9),(10),(11),(12),(13),(14),(15),(16),(17),(18),(19),(20),(21),(22),(23),(24),(25),(26),(27),(28),(29),(30),(31),(32),(33),(34),(35),(36),(37),(38),(39),(40),(41)	ASTM F963:2023-4.3.8: Presence of Phthalates in Plasticized Materials	Pass

****

To be continued

Authorized By :
For Intertek Testing Services
(Tianjin) Ltd.

David Zhang
Asst.General Manager

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司

1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384

Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

1. Toy Tests

As per ASTM Standard Consumer Safety Specification for Toy Safety F963-23.

Appropriate age group for testing： From 3 to 8 years

The submitted samples were undergone the use and abuse tests in accordance with The Federal Hazardous Substances Act (FHSA), Title 16, Code of Federal Regulations:

Test	FHSA	Parameter
Tip over test	Section 1500.53(b)	3 times
Torque test	Section 1500.53(e)	4 in-lbf
Tension test	Section 1500.53(f)	15 lbf
Compression test	Section 1500.53(g)	30 lbf

Section	Testing Items	Assessment
4.1	Material Quality	P
4.2	Flammability	P (See test data #1)
4.3.7	Stuffing Materials	NA
4.4	Electrical/Thermal Energy	NA
4.5	Sound-Producing Toys	P
4.6.1	Toys Intended for Children under 36 Months (Small Objects)	NA
4.6.2	Mouth-Actuated Toys	NA
4.6.3	Toys And Games for 36 Months to 72 Months (Small Part Warning)	P#
4.7	Accessible Edges	P
4.8	Projections	NA
4.9	Accessible Points	P
4.10	Wires Or Rods	NA
4.11	Nails And Fasteners	P
4.12	Plastic Film	P
4.13	Folding Mechanisms and Hinges	NA
4.14	Cords, Straps, and Elastics	NA
4.15	Stability and Over-Load Requirements	P
4.16	Confined Spaces	NA
4.17	Wheels, Tires and Axles	P
4.18	Holes, Clearance, and Accessibility of Mechanisms	P
4.19	Simulated Protective Devices	NA
4.20	Pacifiers	NA
4.21	Projectile Toys	NA
4.22	Teethers and Teething Toys	NA
4.23	Rattles	NA

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

Section	Testing Items	Assessment
4.24	Squeeze Toys	NA
4.25	Battery-Operated Toys	P (See test data #2)
4.26	Toys Intended to be Attached to a Crib or Playpen	NA
4.27	Stuffed and Beanbag-Type Toys	NA
4.28	Stroller and Carriage Toys	NA
4.29	Art Materials	NA
4.30	Toy Gun Marking	NA
4.31	Balloons	NA
4.32	Certain Toys with Nearly Spherical Ends	NA
4.33	Marbles	NA
4.34	Balls	NA
4.35	Pompoms	NA
4.36	Hemispheric-Shaped Objects	NA
4.37	Yo Yo Elastic Tether Toys	NA
4.38	Magnets	NA
4.39	Jaw Entrapment in Handles and Steering Wheels	NA
4.40	Expanding Materials	NA
4.41	Toy Chests	NA
5	Labelling Requirements	P#
6	Instructional Literature	P#
7	Producer's Markings	
7.1	Name and Address of Producer/Distributor	P#
7.2	Battery-powered Ride-on Toys	P#
7.3	Toy Chests	NA

Remark: The submitted samples were undergone the tests in accordance with Section 8.5 through Section 8.18 and 8.21 through 8.26 on normal use, abuse and specific tests for different types of toys whichever is applicable.

P = Pass **F = Fail** NA = Not Applicable

=Only artwork of label, instruction and packaging were provided by applicant.

Test data #1

Flammability Test- Solid & Plush toys

Result = Did Not Ignite

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

Test data #2

Battery-Operated Toys

As per ASTM F963-23 consumer safety specification for toy safety section 4.25, 5.14, 6.5 and 6.6

Appropriate age group for testing：From 3 to 8 years

Type of battery：12V 6FM7　Lead-Acid battery×1 ；　1.5 V AAA×2

Charger type：INPUT: 100-240　V A.C. ; OUTPUT: 12 V D.C.

Model：JT-DC120V1000-D

Electric operated function：D.C. motor driver；sound；light

Section	Testing Items	Assessment
4.25.1	Battery Marking	P
4.25.2	Maximum Allowable Direct Current Potential	P
4.25.3	Protection Against Charging Non-Rechargeable Battery	P
4.25.4	Batteries Accessible	P
4.25.5	Isolation of Batteries of Different Types or Capacities	NA
4.25.6	Temperature of Battery Surface	P
4.25.7	Temperature of Battery Surface or Combustion Hazard after Normal Use and Abuse Test	P
4.25.8	Packaging and Instruction Requirement	
	- 6.5 Instruction on Safe Battery Usage	P#
4.25.9	Battery-Powered Ride-on Toys	P#
4.25.10	Toys that contain secondary cells or secondary batteries	NA

Remark：P = Pass；**F = Fail**；NA = Not Applicable

=Only artwork of label, instruction and packaging were provided by applicant.

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

2. Physical and mechanical test

As per U.S. Code of Federal Regulations Title 16 Part 1500.50, the hazards of sharp points, sharp edge and small parts are assessed both before and after applicable use and abuse tests.

Applicant's specified age group for testing : From 3 to 8 years

	No. Of Sample Tested	Sharp Point (1500.48)	Sharp Edge (1500.49)	Small Part (1501)
As Received	1	P	P	NA
Impact (1500.53(b))	1	P	P	NA
Flexure (1500.53(d))	0	NA	NA	NA
Torque (1500.53(e))	1	P	P	NA
Tension (1500.53(f))	1	P	P	NA
Compression (1500.53(g))	1	P	P	NA

Remark : P = Pass
F = Fail
NA = Not Applicable

3. Small Part Test

As per U.S. Code of Federal Regulations Title 16 Part 1501, the components of the submitted samples were assessed for any small part before and after the appropriate use and abuse tests of 16 CFR 1500.51 and 16 CFR1500.52.

No. of sample tested: 3

Applicant's specified age group for testing: From 3 to 8 years

Result:

This section applies to all toys and other articles intended for use by children under 3 years (36 months) of age. This section was not applicable to the submitted samples.

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

4. Tracking label assessment

As per consumer product safety improvement act (CPSIA) 2008 section 103 tracking labels for children products

tracking label found on the packaging:

Name of manufacturer / importer / private labeler:	Jiaxing Haifa import and export co., ltd
Location of production:	No.233, Chang 'an North Road, Wuyuan Street, Haiyan County, Jiaxing City, Zhejiang Province China
Date code:	January 8(th), 2026
Cohort information:	LB-9911

Tracking label found on the products:

Name of manufacturer / importer / private labeler:	Jiaxing Haifa import and export co., ltd
Location of production:	No.233, Chang 'an North Road, Wuyuan Street, Haiyan County, Jiaxing City, Zhejiang Province China
Date code:	January 8(th), 2026
Cohort information:	LB-9911

note: the tracking label assessment was based on the submitted sample and the information provided by the applicant. There was no verification on the validity of such information. Only artwork of tracking label were provided by applicant.

5.Flammability Test

As per U.S. Code Of Federal Regulations Title 16 Part 1500.44 For Rigid and Pliable Solids.

Result =Did Not Ignite

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road, High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

6. Total Lead (Pb) Content for Non-surface Coating

As per section 4.3.5 of the ASTM standard consumer safety specification on toy safety F963-23, test method CPSC-CH-E1001-08.3 and CPSC-CH-E1002-08.3, were used and total Lead content was determined by Inductively Coupled Argon Plasma Spectrometry.

Test Item	Result in ppm										Reproting Limit (ppm)	Limit (ppm)
	(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)		
Lead(Pb)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	100

Test Item	Result in ppm										Reproting Limit (ppm)	Limit (ppm)
	(11)	(12)	(13)	(14)	(15)	(16)	(17)	(18)	(19)	(20)		
Lead(Pb)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	100

Test Item	Result in ppm										Reproting Limit (ppm)	Limit (ppm)
	(21)	(22)	(23)	(24)	(25)	(26)	(27)	(28)	(29)	(30)		
Lead(Pb)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	100

Test Item	Result in ppm										Reproting Limit (ppm)	Limit (ppm)
	(31)	(32)	(33)	(34)	(35)	(36)	(37)	(38)	(39)	(40)		
Lead(Pb)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	100

Test Item	Result in ppm						Reproting Limit (ppm)	Limit (ppm)
	(42)	(43)	(44)	(45)	(46)	(47)		
Lead(Pb)	29	34	10	10	ND	31	10	100

Remark： ppm = parts per million based on dry weight of sample = mg/kg
ND= Not detected (Less than reporting limit)

Tested Components：See component list in the last section of this report.

7. Total Lead (Pb) Content for Surface Coating

As per section 4.3.5 of the ASTM standard consumer safety specification on toy safety F963-23, test method CPSC-CH-E1003-09.1 was/were used and total Lead content was determined by Inductively Coupled Argon Plasma Spectrometry.

Test Item	Result in ppm	Reproting Limit (ppm)	Limit (ppm)
	(41)		
Lead(Pb)	ND	20	90

Remark： ppm = parts per million based on dry weight of sample = mg/kg
ND= Not detected (Less than reporting limit)

Tested Components：See component list in the last section of this report.

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

8. Heavy Metal Elements Analysis in Surface Coating

With reference to Section 4.3.5 of the ASTM Standard Consumer Safety Specification on Toy Safety F963-23, test method Section 8.3.1 of ASTM F963-23 were used and total heavy elements content were determined by Inductively Coupled Argon Plasma Spectrometry.

Test Item	Result (mg/kg) (41)	Reproting Limit (mg/kg)	Limit (mg/kg)
Tot. Barium (Ba)	56	10	1000(Soluble)
Tot. Lead (Pb)	ND	20	90(Total/Soluble)
Tot. Cadmium (Cd)	ND	10	75(Soluble)
Tot. Antimony (Sb)	ND	10	60(Soluble)
Tot. Selenium (Se)	ND	10	500(Soluble)
Tot. Chromium (Cr)	112#1	10	60 (Soluble)
Tot . Mercury (Hg)	ND	10	60(Soluble)
Tot. Arsenic (As)	25#1	10	25(Soluble)

Remark：Tot. = Total
ND= Not detected (Less than reporting limit)
#1 = Exceeded soluble limit Soluble heavy metal elements analysis should be conducted.

Tested Components：See component list in the last section of this report.

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

9. Heavy Metal Elements Analysis in Non-surface Coating Materials

With reference to Section 4.3.5 of the ASTM Standard Consumer Safety Specification on Toy Safety F963-23, test method Section 8.3.1 of ASTM F963-23 were used and total heavy elements content were determined by Inductively Coupled Argon Plasma Spectrometry.

Test Item	Result (mg/kg)										Reproting Limit (mg/kg)	Limit (mg/kg)
	(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)		
Tot. Barium (Ba)	13	ND	ND	14	ND	ND	ND	ND	378	15	10	1000(Soluble)
Tot. Lead (Pb)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	100(Total)
Tot. Cadmium (Cd)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	75(Soluble)
Tot. Antimony (Sb)	ND	ND	ND	ND	ND	ND	ND	ND	94#1	ND	10	60(Soluble)
Tot. Selenium (Se)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	500(Soluble)
Tot. Chromium (Cr)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	60 (Soluble)
Tot . Mercury (Hg)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	60(Soluble)
Tot. Arsenic (As)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	25(Soluble)

Test Item	Result (mg/kg)										Reproting Limit (mg/kg)	Limit (mg/kg)
	(11)	(12)	(13)	(14)	(15)	(16)	(17)	(18)	(19)	(20)		
Tot. Barium (Ba)	ND	21	ND	ND	ND	16	17	ND	ND	19	10	1000(Soluble)
Tot. Lead (Pb)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	100(Total)
Tot. Cadmium (Cd)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	75(Soluble)
Tot. Antimony (Sb)	ND	56	ND	ND	ND	ND	ND	ND	ND	ND	10	60(Soluble)
Tot. Selenium (Se)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	500(Soluble)
Tot. Chromium (Cr)	ND	175#1	ND	ND	ND	ND	ND	ND	ND	ND	10	60 (Soluble)
Tot . Mercury (Hg)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	60(Soluble)
Tot. Arsenic (As)	ND	ND	ND	ND	ND	19	ND	ND	ND	ND	10	25(Soluble)

Test Item	Result (mg/kg)										Reproting Limit (mg/kg)	Limit (mg/kg)
	(21)	(22)	(23)	(24)	(25)	(26)	(27)	(28)	(29)	(30)		
Tot. Barium (Ba)	ND	12	590	ND	ND	ND	ND	ND	ND	ND	10	1000(Soluble)
Tot. Lead (Pb)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	100(Total)
Tot. Cadmium (Cd)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	75(Soluble)
Tot. Antimony (Sb)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	60(Soluble)
Tot. Selenium (Se)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	500(Soluble)
Tot. Chromium (Cr)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	60 (Soluble)
Tot . Mercury (Hg)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	60(Soluble)
Tot. Arsenic (As)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	25(Soluble)

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

Test Item	Result (mg/kg)										Reproting Limit (mg/kg)	Limit (mg/kg)
	(31)	(32)	(33)	(34)	(35)	(36)	(37)	(38)	(39)	(40)		
Tot. Barium (Ba)	ND	ND	21	26	254	ND	ND	ND	ND	ND	10	1000(Soluble)
Tot. Lead (Pb)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	100(Total)
Tot. Cadmium (Cd)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	75(Soluble)
Tot. Antimony (Sb)	ND	ND	ND	ND	ND	ND	ND	112#1	89#1	12	10	60(Soluble)
Tot. Selenium (Se)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	500(Soluble)
Tot. Chromium (Cr)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	60 (Soluble)
Tot . Mercury (Hg)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	60(Soluble)
Tot. Arsenic (As)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10	25(Soluble)

Remark：Tot. = Total
ND= Not detected (Less than reporting limit)
#1 = Exceeded soluble limit

Tested Components：See component list in the last section of this report.

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司

1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384

Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

10. Soluble Elements Analysis (ASTM F963-23)

As per section 4.3.5.1(2) and 4.3.5.2(2)(b) of the ASTM standard consumer safety specification on toy safety F963-23, acid extraction method was used and heavy metal elements migration content were determined by Inductively Coupled Argon Plasma Spectrometry.

Test Item	Result (mg/kg)					Reporting Limit (mg/kg)	Limit (mg/kg)
	(9)	(12)	(38)	(39)	(41)		
Sol. Barium (Ba)	ND	ND	ND	ND	ND	5	1000
Sol. Lead (Pb)	ND	ND	ND	ND	ND	5	90
Sol. Cadmium (Cd)	ND	ND	ND	ND	ND	5	75
Sol. Antimony (Sb)	ND	ND	ND	ND	ND	5	60
Sol. Selenium (Se)	ND	ND	ND	ND	ND	5	500
Sol. Chromium (Cr)	ND	ND	ND	ND	33	5	60
Sol. Mercury (Hg)	ND	ND	ND	ND	ND	5	60
Sol. Arsenic (As)	ND	ND	ND	ND	ND	2.5	25

Remark： mg/kg = milligram per kilogram =ppm
Sol. = Soluble
ND= Not detected (Less than reporting limit)

Tested components：See component list in the last section of this report.

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

11. Total Lead (Pb) Content In Surface Coating

As per standard operating procedure for determining Lead (Pb) in paint and other similar surface coatings (April 26, 2009), test method CPSC-CH-E1003-09 was used and total Lead content was determined by Inductively Coupled Argon Plasma Spectrometry.

Tested Component	Result (ppm)	Limit (ppm)
(41)	<20	90

Remark：ppm = Parts per million based on dry weight of sample = mg/kg
< = Less Than

Tested Components：See component list in the last section of this report.

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

12. Total Lead (Pb) Content In Non-Surface Coating Materials (Substrate)

As per standard operating procedures for determining total Lead (Pb) in children's products, test method(s) CPSC-CH-E1002-08.1 and CPSC-CH-E1001-08.1 were used and total Lead content was determined by Inductively Coupled Argon Plasma Spectrometry.

Tested Component	Result (ppm)	Limit (ppm)
(1)	<10	100
(2)	<10	100
(3)	<10	100
(4)	<10	100
(5)	<10	100
(6)	<10	100
(7)	<10	100
(8)	<10	100
(9)	<10	100
(10)	<10	100
(11)	<10	100
(12)	<10	100
(13)	<10	100
(14)	<10	100
(15)	<10	100
(16)	<10	100
(17)	<10	100
(18)	<10	100
(19)	<10	100
(20)	<10	100
(21)	<10	100
(22)	<10	100
(23)	<10	100
(24)	<10	100
(25)	<10	100
(26)	<10	100
(27)	<10	100
(28)	<10	100
(29)	<10	100
(30)	<10	100
(31)	<10	100
(32)	<10	100
(33)	<10	100
(34)	<10	100
(35)	<10	100
(36)	<10	100
(37)	<10	100
(38)	<10	100
(39)	<10	100
(40)	<10	100
(42)	29	100
(43)	34	100
(44)	10	100
(45)	10	100
(46)	<10	100
(47)	31	100

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

Remark：ppm = Parts per million = mg/kg
< = Less Than

Tested Components：See component list in the last section of this report.

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司

1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384

Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

13. Phthalate Content

With reference to CPSC-CH-C1001-09.4, by Gas Chromatographic-Mass Spectrometric (GC-MS) analysis.

Test item	Result (%)										Limit (%) (Max.)
	(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	
Dibutyl phthalate (DBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-(2-ethylhexyl) phthalate (DEHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Benzyl butyl phthalate (BBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Diisononyl phthalate (DINP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Diisobutyl phthalate (DIBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-n-pentyl phthalate (DPENP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-n-hexyl phthalate (DHEXP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Dicyclohexyl phthalate (DCHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1

Test item	Result (%)										Limit (%) (Max.)
	(11)	(12)	(13)	(14)	(15)	(16)	(17)	(18)	(19)	(20)	
Dibutyl phthalate (DBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-(2-ethylhexyl) phthalate (DEHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Benzyl butyl phthalate (BBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Diisononyl phthalate (DINP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Diisobutyl phthalate (DIBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-n-pentyl phthalate (DPENP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-n-hexyl phthalate (DHEXP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Dicyclohexyl phthalate (DCHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1

Test item	Result (%)										Limit (%) (Max.)
	(21)	(22)	(23)	(24)	(25)	(26)	(27)	(28)	(29)	(30)	
Dibutyl phthalate (DBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-(2-ethylhexyl) phthalate (DEHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Benzyl butyl phthalate (BBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Diisononyl phthalate (DINP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Diisobutyl phthalate (DIBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-n-pentyl phthalate (DPENP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-n-hexyl phthalate (DHEXP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Dicyclohexyl phthalate (DCHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

Test item	Result (%)											Limit (%) (Max.)
	(31)	(32)	(33)	(34)	(35)	(36)	(37)	(38)	(39)	(40)	(41)	
Dibutyl phthalate (DBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-(2-ethylhexyl) phthalate (DEHP)	ND	ND	ND	ND	0.08	ND	ND	ND	ND	ND	ND	0.1
Benzyl butyl phthalate (BBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Diisononyl phthalate (DINP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Diisobutyl phthalate (DIBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-n-pentyl phthalate (DPENP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Di-n-hexyl phthalate (DHEXP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1
Dicyclohexyl phthalate (DCHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.1

The above limit was quoted according to 16 CFR part 1307 approved by U.S. Consumer Product Safety Commission (CPSC) for prohibition of children's toys and child care articles containing specified phthalates.

Remark：ND = Not Detected
Detection Limit = 0.01%

Tested Component(s): See component list in the last section of this report.

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司

1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384

Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

14.Phthalates Content (ASTM F963-23)

With reference to CPSC-CH-C1001-09.4, by Gas Chromatographic-Mass Spectrometric (GC-MS) analysis.

Test item	Result (%)										Detection Limit (%)	Limit (%) (Max.)
	(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)		
Dibutyl phthalate (DBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-(2-ethylhexyl) phthalate (DEHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Benzyl butyl phthalate (BBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Diisononyl phthalate (DINP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Diisobutyl phthalate (DIBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-n-pentyl phthalate (DPENP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-n-hexyl phthalate (DHEXP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Dicyclohexyl phthalate (DCHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1

Test item	Result (%)										Detection Limit (%)	Limit (%) (Max.)
	(11)	(12)	(13)	(14)	(15)	(16)	(17)	(18)	(19)	(20)		
Dibutyl phthalate (DBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-(2-ethylhexyl) phthalate (DEHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Benzyl butyl phthalate (BBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Diisononyl phthalate (DINP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Diisobutyl phthalate (DIBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-n-pentyl phthalate (DPENP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-n-hexyl phthalate (DHEXP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Dicyclohexyl phthalate (DCHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1

Test item	Result (%)										Detection Limit (%)	Limit (%) (Max.)
	(21)	(22)	(23)	(24)	(25)	(26)	(27)	(28)	(29)	(30)		
Dibutyl phthalate (DBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-(2-ethylhexyl) phthalate (DEHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Benzyl butyl phthalate (BBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Diisononyl phthalate (DINP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Diisobutyl phthalate (DIBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-n-pentyl phthalate (DPENP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-n-hexyl phthalate (DHEXP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Dicyclohexyl phthalate (DCHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

Test item	Result (%)											Detection Limit (%)	Limit (%) (Max.)
	(31)	(32)	(33)	(34)	(35)	(36)	(37)	(38)	(39)	(40)	(41)		
Dibutyl phthalate (DBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-(2-ethylhexyl) phthalate (DEHP)	ND	ND	ND	ND	0.08	ND	ND	ND	ND	ND	ND	0.01	0.1
Benzyl butyl phthalate (BBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Diisononyl phthalate (DINP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Diisobutyl phthalate (DIBP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-n-pentyl phthalate (DPENP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Di-n-hexyl phthalate (DHEXP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1
Dicyclohexyl phthalate (DCHP)	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0.01	0.1

Remark：ND = Not Detected(Less than detection limit)

Tested Components：See component list in the last section of this report.

****

To be continued

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司

1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384

Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Test Report

NUMBER : TSNH00578176

Test components:
(1) black plastic of sample (A) used.(body)
(2) pink plastic of sample (B) used.(body)
(3) white plastic of sample (C) used.(body)
(4) black plastic of all samples used.(bumper)
(5) grey plastic of all samples used.(door,big panel)
(6) grey plastic of all samples used.(steering wheel)
(7) white plastic of all samples used.(buttons on steering wheel)
(8) grey plastic of all samples used.(seat)
(9) black plastic of all samples used.(buttons on panel,panel)
(10)black plastic of all samples used.(USB on panel)
(11)black plastic of all samples used.(MIC on panel)
(12)black plastic of all samples used.(charging hole under the seat)
(13)red plastic with white painting of all samples used.(power button)
(14)black plastic with white painting of all samples used.(speed button)
(15)transparent plastic of all samples used.(wind screen)
(16)black plastic of all samples used.(pedal)
(17)black plastic of all samples used.(wheel)
(18)grey plastic of all samples used.(wheel cap)
(19)transparent plastic of all samples used.(front light)
(20)silver plastic of all samples used.(front light)
(21)yellow plastic of all samples used.(light on wind screen)
(22)silver plastic of all samples used.(RAM logo)
(23)red plastic of all samples used.(lock of door)
(24)red plastic of all samples used.(rear light)
(25)white plastic of all samples used.(electrical machinery)
(26)light white plastic of all samples used.(electrical machinery)
(27)black plastic of all samples used. (charger head)
(28)black plastic of all samples used. (charger wire)
(29)black plastic of all samples used. (small charger head)
(30)white plastic of all samples used. (remote control)
(31)black plastic of all samples used. (remote control buttons)
(32)red plastic of all samples used. (remote control light)
(33)black plastic of all samples used. (safety belt buckle)
(34)black fabric of all samples used. (safety belt buckle)
(35)black synthetic leather of all samples used. (safety belt buckle)
(36)black/white/transparent sticker of all samples used.(panel)
(37)white/red/black sticker of all samples used.(warning label)
(38)silver sticker of all samples used.(rearview mirror)
(39)silver sticker of all samples used.(rear light)
(40)multicolor sticker of all samples used.(body)
(41)black coating on metal of all samples used.(axle)
(42)silvery metal without coating of all samples used. (axle)
(43)silvery metal screw of all samples used.(body)
(44)silvery color metal of all samples used.(charger head)
(45)silvery color metal of all samples used.(small charger head)
(46)silvery color metal of all samples used.(charging hole under the seat)
(47)silvery color metal of all samples used.(USB on panel)

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司
1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384
Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com

Total Quality. Assured.

Test Report

NUMBER : TSNH00578176

Date Sample Received : Jan 16,2026
Testing Period : Jan 16,2026 to Jan 28,2026

****

End of report

Intertek Testing Service (Tianjin) Ltd.
天祥(天津)质量技术服务有限公司

1-6/F.,Building B,No.7,Guiyuan Road,
High-Tech Zone,Tianjin,China
天津市高新区桂苑路7号B座1-6层
邮编 300384

Tel +86 22 8371 4973
hardlines.tianjin@intertek.com
www.intertek.com.cn
www.intertek.com